



DP 304554




304554 3/8 -3,96 2 PLC 28 After U-S operation to hold 50 Ultrasonically Welded Wire Retention Area SRE (Rear) Fan wires on new rotor Alternator Front for both views for New Rotor SRE (Rear) Fan Before U-S operation to hold wires on new rotor 82 3.5 4.9 -2 PLACES

Fishe 8 Ø 8.58 8.50 REF # Comment of the state of the s -1.6 R . 2 PLACES -3.0 R · 2 PLACES -3.9 - 2 PLACES STRIP LEAD FOR DISTANCE SHOWN - Z PLACES ... VIEW OF SLIP RING BEFORE FORMING LEADS . 63.3 59.3 - 46.0 44.0 ) · · · · · · 20.3 20.0 REF 37.4 2 PLACES --2 PLACES Ø 14.85 14.55 REF 2 PLACES. Ø 8.48 8.40 REF

DP 304554 4/8



Views showing connection of Slip Ring & Coil



66 (06 Alternator Rotor Repair Cap

TView of New Rotor

4.1. jue 15

The state of the s

